

=====

**MEASURE PICTURE #4** INCH, HALF, QUARTER, and EIGHT INCH

**BE SURE TO CHECK EACH INSTRUCTION WHEN YOU COMPLETE IT.**

- 1. Point E is on Line A B, 3" from Point A.
- 2. Point F is on Line B D, 3-3/4" from Point B.
- 3. Point G is on Line C D, 4-3/4" from Point C.
- 4. Point H is on Line C D, 4-1/2" from Point C.
- 5. Point I is on Line C D, 3-3/8" from Point C.
- 6. Point J is on Line C D, 1-1/8" from Point C.
- 7. Point K is on Line A C, 4-3/4" from Point A.
- 8. Point L is on Line A C, 3-3/4" from Point A.
- 9. Connect Point (E and F).
- 10. Connect Point (E and K).
- 11. Connect Point (L and F).
- 12. Point M is on Line L F, 1-1/8" from Point L.
- 13. Point N is on Line L F, 4-3/4" from Point L.
- 14. Connect Point (N and G).
- 15. Connect Points (M and J).
- 16. Point O is on Line M J, 1-1/2" from Point M.
- 17. Point P is on Line N G, 1-1/2" from Point N.
- 18. Connect Points (O and P).
- 19. Point Q is on Line O P, 2-1/4" from Point O.
- 20. Point R is on Line O P, 3-3/8" from Point O.
- 21. Connect Points (R and H).
- 22. Connect Points (Q and I).
- 23. On Line N P, start at Point N and make a dot every 3/8" to Point P.
- 24. On Line M O, start at Point M and make a dot every 3/8" to Point O.
- 25. Connect the dots on Line M O straight across to the dots on Line N P.
- 26. On Line O J, start at Point O and make a dot every 3/8" to Point J.
- 27. On Line Q I, start at Point Q and make a dot every 3/8" to Point I.
- 28. Connect the dots on Line O J straight across to the dots on Line Q I.
- 29. What Does your Picture Show? \_\_\_\_\_

**END**

